

1984  
CODE 51  
FUEL INJECTION (TBI)

CHECK THAT ALL PINS ARE FULLY INSERTED IN THE SOCKET.  
IF OK, REPLACE PROM, CLEAR MEMORY, AND RECHECK. IF  
CODE 51 REAPPEARS, REPLACE ECM.

---

CODE 55  
FUEL INJECTION

REPLACE ELECTRONIC CONTROL MODULE (ECM).

CLEAR CODES AND CONFIRM "CLOSED LOOP" OPERATION AND NO "CHECK ENGINE" LIGHT.