

1984
CODE 51
FUEL INJECTION (TBI)

CHECK THAT ALL PINS ARE FULLY INSERTED IN THE SOCKET.
IF OK, REPLACE PROM, CLEAR MEMORY, AND RECHECK. IF
CODE 51 REAPPEARS, REPLACE ECM.

CODE 55
FUEL INJECTION

REPLACE ELECTRONIC CONTROL MODULE (ECM).

CLEAR CODES AND CONFIRM "CLOSED LOOP" OPERATION AND NO "CHECK ENGINE" LIGHT.